



SERVICE INFORMATION LETTER

SIL 0191
Page 1 of 2

- DATE: August 14, 2019
1. SUBJECT: Lamiflex Bearing Discontinuation
 2. MODEL: F-28, F-28A, F-28C, F-28C-2, F-28C-2R, F-28F, 280, 280C, 280F, and 280FX
 3. EFFECTIVITY: All
 4. BACKGROUND:

This Service Information Letter (SIL) is to make aircraft owners/operators aware that Enstrom is discontinuing the Lamiflex main rotor thrust bearings (P/N 28-14320-15). Enstrom has a limited supply of the bearings and once current supplies are exhausted, they will no longer be available. The Lamiflex bearings are being replaced with a tension-torsion (T-T) strap configuration.

5. COMPLIANCE:

When Lamiflex bearings are no longer available, owners/operators will need to convert their aircraft to a T-T strap configuration. Refer to Table 1.

Table 1: Vendor Information

Part Number*	Manufacturer*	
AA-ECD-084-280 (STC SR03465CH)	Airwolf Aerospace LLC 15369 Madison Rd. Middlefield, OH 44062-8404	(440) 632-1687 (440) 632-1685 Fax www.airwolfaerospace.com info@airwolfaerospace.com

6. SPECIAL TOOLS: N/A
7. MAN-HOURS: N/A
8. WARRANTY: Per Enstrom Helicopter Warranty policy

August 14, 2019

9. WEIGHT CHANGE: N/A

10. LOG BOOK ENTRY: N/A

11. REPETITIVE INSPECTIONS: N/A