

IMPORTANT SAFETY NOTE

POST INSTALLATION TEST FLIGHT

It can be expected that there will be a significant change in the collective pressures resulting from the change to TT straps

Expect significant light collective forces during initial test flights until the collective spring capsule has been adjusted.

PLEASE BE SURE TO INFORM THE PILOT PRIOR TO TEST FLIGHT

